

EPA Technician Certification

Tips on Passing the Examination

1. Review the training material prior to the test date.
2. Answer the questions listed at the end of each section.
3. Check your answers. The minimum passing score is 70%, but we recommend that you repeat the training until 90% are answered correctly.
4. Make note of confusing topics, and prior to the test, ask the instructor to clarify any uncertainties.
5. Bring your driver's license to the testing site because personal identification is required to take the exam, no exceptions!
6. Dress comfortably and arrive on time. Prepare for the test mentally, physically, and emotionally.
7. During the review listen actively, focus on the information being discussed, take useful notes, highlight key information, and follow instructions. Participate by asking questions to clarify only uncertainties. Don't waste time arguing points.
8. Look for clues that highlight important information; e.g.: transparencies, underlined material, or the instructor's verbal clues.
9. Don't waste time during breaks! Use some of that time to review notes, key information, and the study questions until clearly understood.
10. The test is multiple choice (A, B, C, or D); however, carefully read the test questions and all possible answers before making your selection. More importantly, mark all answers on the answer sheet and not in the test booklet. Marking in the test booklet will result in disqualification.
11. Do not change answers unless you are absolutely sure that your selection is not correct, and mainly because, the first selection is usually right 80% of the time.
12. During the test, stay relaxed. If you start to get anxious close your eyes and take deep breaths.
13. Before turning in the test, check the answer sheet for errors and/or skipped questions.

Should additional information be desired, please contact AC/C TECH at 317-545-7071. Good Luck!